

TUV INDIA PVT. LTD. 8-3-1092/93, NIAR, Roj Bhavan Road Somajiguda, Hyderabad – 500 082

INSPECTION REPORT

Project:		101000000000 1010000000000000000000000		-	IRN Number : 8107643823	
Main Order Number:		On :				
	33, Date:03-02-2011	2000				
Sub-Order Number : -		On :				
nspection Da	ate: 04 February 2011	Order Statu	JS:	Comple	te Incom	plete
THE FOLLO	WING WAS/WERE FINALLY I	INSPECTE	D:			
P.O. SR.NO	ITEM DESCRIPTION		UNIT	QUANTITY		
				AS PER P	O. OFFERED	RELEASED
Functioning of the whole plant to convert Waste Plastic and Rubber into Fuel Oil.			24)			
	pection : ssed the Pilot plant located at Pasi	hamaylaran	n indust	rial estate.		
2) Obse	ssed the Pilot plant located at Pasi rved in the plant-convert Plastics/	tyre into Fue	el oil is	existing ph		-
1) Witne	ssed the Pilot plant located at Pasi	tyre into Fue	el oil is	existing ph		-
1) Witne	ssed the Pilot plant located at Pasi rved in the plant-convert Plastics/	tyre into Fue	el oil is	existing ph		-
1) Witne	ssed the Pilot plant located at Pasi rved in the plant-convert Plastics/	tyre into Fue	el oil is	existing ph		-
1) Witne	ssed the Pilot plant located at Pasi rved in the plant-convert Plastics/	tyre into Fue	el oil is	existing ph		-
1) Witne	ssed the Pilot plant located at Pasi rved in the plant-convert Plastics/	tyre into Fue	el oil is	existing ph		
1) Witne 2) Obse 3) Obse	ssed the Pilot plant located at Pasi rved in the plant-convert Plastics/	tyre into Fue	el oil is	existing ph		
1) Witne 2) Obse 3) Obse	ssed the Pilot plant located at Pasi rved in the plant convert Plastics/lived the plastic material is being for	tyre into Fue ed at one er	el oil is	existing phother in the color of the color o	ming out at the o	